

	1	2	3	4	5	6	7	8	9	10	
A								图纸提供单位			A
B								材质工艺要求			B
C								刀模线			C
D								纹理方向			D
E								用量：1			E
F								包装名称：快速指引（巴西）			F
								料号：3.H-7103-G01BM3-009			
								型号：G01BM3			
								设计师：宋晓雷			
								日期：2026-05-15			
								单位：mm			
								比例：1:1			
	1	2	3	4	5	6	7	8	9	10	

